

EP AND PU SEALER AND COATING

The cleaning system to be selected depends on the size of the floor, its use and the base treatment.

Regular cleaning	Arturo EP & PU Sealer & Coatings		Frequency			Equipment/materials required
	Method	Product	Daily	Weekly	Periodically	
	Dust-collecting system Damp mop Scrubber-dryer	RZ Elastic Wipe Care RZ Floor Care ◆ 1:200	●	●		
Interim cleaning	Cleansing activities. Apply when needed.	RZ PUR Cleaner ◆ 1:200 In specific cases up to 1:10 possible			●	White 3M Pad (soft cleaning) Red 3M Pad (stronger dirt content) RZ Microfibre Mop
Thorough cleaning**	Wet scrubbing and suction. At least once a year.	RZ Basic Cleaner Universal ◆ 1:10 up to 1:1			●	Red 3M Pad RZ Microfibre Mop

◆ = Product dose / depend on degree of contamination * = Improvement from the step security ** = when needed, at least once a year



Phone number.: +49 (0)731 4097 – 405
email: info@rz-systeme.de

Important information

Dust and loose dirt adversely affect the friction of the floor surface. It is advisable to remove loose dirt and dust on a daily basis.

Note: Protective treatments higher than R10 slip resistance are not possible by applying a polymer dispersion!

Fine cleaning

Remove loose dirt with a vacuum cleaner or with a dust-collecting cleaning system. Scrub with a white pad and then remove water by suction. Rinse, remove water again by suction and leave to dry.

Uzin Utz Nederland bv operates the quality assurance system in accordance with NEN-EN ISO-9001/14001 and is certified for this by TÜV Nederland QA. This means that deliveries are made in accordance with the product and process specifications drawn up for this system. Products and services supplied by Uzin Utz Nederland bv also comply with the description in these technical specifications. As different site conditions and working practices are unknown, Uzin Utz Nederland bv accepts no liability for any damage resulting from any use of its products. With the publication of this data sheet, all previously published data sheets concerning this product become invalid. © Uzin Utz Nederland bv. All rights reserved. Copying and/or reproduction of this publication, in whatever form, is not permitted without the written permission of Uzin Utz Nederland bv. | 03.2020

Arturo | A brand of Uzin Utz Group

EN | Uzin Utz Nederland bv | Bouwstraat 18 | 7483 PA Haaksbergen | Telephone +31 53 5737373 | E-mail info@arturoflooring.com | Internet www.arturoflooring.com