

Taski Cleaning recommendations

ELECTRICALLY CONDUCTING SELF-SMOOTHING FLOOR COATINGS

The cleaning system to be selected depends on the size of the floor, its use and the base treatment.

Base treatment	Arturo electrically conducting self-levelling floor coating	Product	Frequency			Equipment/materials required
	Method		Daily	Weekly	Periodically	
Base treatment	Electrically conducting dispersion to avoid the build up of static charge	Taski Jontec ESD ◆ 100%			●	TASKI applicator
Regular cleaning	Dust-collecting system Damp mop Scrubber-dryer	Taski Jontec Destat* ◆ 3.5% 300	●	●		TASKI Flortex / TASKI Lamello TASKI Duo mop system TASKI Swingo scrubber-dryer
Interim cleaning	Cleansing activities. Apply when needed.	Taski Jontec Forward ◆ 5% Taski Jontec Destat* ◆ 7%		●		Blue pad
Thorough cleaning**	Wet scrubbing and suction. At least once a year.	Taski Jontec Linosafe ◆ 50%			●	Blue 3M pad Green 3M pad

◆ = Product dose * = strongly advised because all other cleaning agents reduce the electrical conductivity of the surface

**= when needed, at least once a year

ELECTRICALLY CONDUCTING SELF-SMOOTHING FLOOR COATINGS



Important information

Dust and loose dirt adversely affect the friction of the floor surface. It is advisable to remove loose dirt and dust on a daily basis (e.g. using the TASKI Lamello system).

Note: Protective treatments higher than R10 slip resistance are not possible by applying a polymer dispersion!

Fine cleaning

Remove loose dirt with a vacuum cleaner or with a dust-collecting cleaning system. Scrub with a red pad and then remove water by suction. Rinse, remove water again by suction and leave to dry.

Uzin Utz Nederland bv operates the quality assurance system in accordance with NEN-EN ISO-9001/14001 and is certified for this by TÜV Nederland QA. This means that deliveries are made in accordance with the product and process specifications drawn up for this system. Products and services supplied by Uzin Utz Nederland bv also comply with the description in these technical specifications. As different site conditions and working practices are unknown, Uzin Utz Nederland bv accepts no liability for any damage resulting from any use of its products. With the publication of this data sheet, all previously published data sheets concerning this product become invalid. © Uzin Utz Nederland bv. All rights reserved. Copying and/or reproduction of this publication, in whatever form, is not permitted without the written permission of Uzin Utz Nederland bv. | 03.2020

Arturo | A brand of Uzin Utz Group

EN | Uzin Utz Nederland bv | Bouwstraat 18 | 7483 PA Haaksbergen | Telephone +31 53 5737373 | E-mail info@arturoflooring.com | Internet www.arturoflooring.com